

54500P

















#### Liner Construction

Inner film (removed after curing)

**Glassfibre-bonded complex** 

Styrene-tight outer film

Protective film(against UV radiation and damage during insertion)



# MANUFACTURING

### ISO 9001 CERTIFIED







# Completion & Packaging



# Quality Control







#### Installation Benefits

- Not weather
  dependent, can line
  anytime of the year
- Can line any shape



### **Fully Deteriorated Culvert**



# Pre-Jetting Lines, CCTV, Marking the laterals



Trenchless, LLC



PRECISION Trenchless, LLC

#### Pull in liner



# Insertion of UV Light source



# Offset joints rehab





#### A 48" Liner In A 24" Manhole



### Liner pulled through middle MH




# Before. During. And After.





### Document Your Curing Process



#### No disruption to traffic flow





### Finished Liner




Before


After



### **Challenging Locations**















THE PRECISION













